



RECAMBIOS INDALO
recambios para el automóvil



ÖLQ - H100873 - LATA 5L ATF DEXRON II (RJ)

GM DEXRON II D

MB 236.9

MAN 339 V-1/339 Z-1

VOITH H55.6335

ZF TE-ML 03D/04D/11A/14A/17C

ALLISON C-4

FORD MERCON